



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 08/26/2014


Reviewed 

Mine Name: South Farm	Permit Number: M/035/0034	Mine Status: Proposed
Operator Name: R.A. Johnson	Inspection Date: 08/18/2014	Permit Fees: Paid
Inspector(s): L. Heppler	Inspection Time: 2:30 PM	Bond Amount: \$14,620
Attendee(s): Blake Thomas-Herriman, Robert Johnson-Opt	Weather: Sunny, Dry	Bond Escalation: 10/15/2010
Inspection Purpose: Operator requested bond release		Prior Inspection: none

Conclusions and Recommendations

This site has never been approved, it is a proposed mine. This site has NOT been reclaimed and the bond would not normally be returned to the operator by OGM, but the site is under a future Herriman City roadway which has a developers construction bond held by Herriman City. A roadway bonded by the city is a post mining land use. Documentation from Herriman City is attached regarding bond release. OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> Permit fee is up to date, no transfers were requested, bond escalation is past due as shown above .	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> Small pit was on site with oversteepended walls.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i> No external drainage problems were noted , but weather was dry.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i> Cast concrete pipe was on site - no rebar reinforcement in noted in pipe, no deleterious materail was noted	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> Roads were in fair condition, no dust suppression at the time of construction	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> No concurrent reclamation was noted at the time of inspection. Mine site is the future site of a Herriman City roadway	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i> No regrading at the site at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i> No soil stockpiles are noted at the time of inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> No new revegetation was noted	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i> This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Herriman City - BThomas@Herriman.org, Operator - Robert Johnson

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M035-SaltLake/M0350034-SouthFarms/inspections/INSP-08182014.pdf



Un-reclaimed site



Cast concrete pipe on site



Operator at mine - Un-reclaimed site



Un-reclaimed site